

# KEARSARGE Southampton 2025

## Annual Solar Site Report

**Prepared by Kearsarge Energy on 2/27/2026**

<b>Site Address:</b>	1370 Majors Path, Southampton, NY 11968
<b>Total 2025 Production in kWh (2/27/25 – 2/26/26)</b>	8,043,893
<b>Atmospheric carbon equivalents</b>	
<b>Tons of CO<sub>2</sub>:</b>	5,957
<b>Gallons of gasoline consumed:</b>	608,112
<b>Major Maintenance or System Modifications:</b>	None
<b>Major System Modifications Planned:</b>	None
<b>Condition of screening and landscaping</b>	Good

### Maintenance Activity Overview

- Daily/Intraday performance and safety checks
- Comprehensive site status check (Quarterly or coincident with reactive maintenance site visits)
- Maintenance highlights
  - ❖ Routine maintenance including inverter, module, and fence repairs
- Annual Site review of all equipment with thermal imaging, along with routine wire management and other site maintenance
- Lawn mowing and site grooming; snow removal as necessary for site access

